



Overview: Part of spill impact on 16" Egbema-Assa trunkline right of way at Obile. Picture was taken during Joint Investigation of 26th May 2012.



Close up: Illegal fitting on 16" Egbema-Assa trunkline at Obile. Picture was taken during Joint Investigation of 26th May 2012.