



Close up: Illegal fittings on 12" Imo River2 pipeline at Odagwa. Picture was taken during Joint Investigation of 5th May 2012.