



Overview: Part of spill impact on Agbada Well34S flowline right of way at Omuohia Omueke. Picture was taken during Joint Investigation of 31<sup>st</sup> May 2012.



Close up: Hacksaw cut on Agbada Well34S flowline at Omuohia Omueke. Picture was taken during Joint Investigation of 31<sup>st</sup> May 2012.