



Close up: Hacksaw cut on Imo River1 Well26L flowline at Owaza. Picture was taken during Joint Investigation of 5<sup>th</sup> May 2012.