



Overview: Part of spill impact on 4" Agbada2 Well48S flowline right of way at Omuohia . Picture was taken during Joint Investigation of 11th May 2012



Close up: Cut section on 4" Agbada2 Well48S flowline at Omuohia . Picture was taken during Joint Investigation of 11th May 2012.