



Overview: Part of spill impact on Benisede Well 1 flowline right of way at Tamogbene. Picture was taken during Joint Investigation of 31st May 2012.



Close up: Hacksaw cut on Benisede Well 1 flowline at Tamogbene. Picture was taken during Joint Investigation of 31st May 2012.