# 

JOINT INVESTIGATION REPORT FOR INCIDENT NO: (Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties) A. GENERAL INFORMATION: 1. Spill incident Number: 900 126 2.Type of incident \* [] 3. Name of Location NEMBE 4. Name of nearest community DGBOLOMABIRIS, State: BAYELSA 6, LGA NEMBE 7. Type of Production facility/Installation WELLHEAD 8. Asset owner/ District NES2 **B. INCIDENT INFORMATION:** 9 Details of incident NOVEMBER 2012. a. Date of incident: 30 TH b. Start date/time of investigation: c. Investigation End date: 285 DEC d. Description of spill point environment ☐Firmed soil Loose soil Previously excavated area ☐Under water □ Swampy Exposed pipe surface Well Plateform (on Water) □Rig e. Description of leak point (tick as applicable); Drilled hole Hack saw cut Explosive tear, ☐ Inward dent. Complete Rupture ☐ Well head tampering ☐Failed Weld-on illegal hot tap valve, ☐ Missing Pipeline/Flowline) ☐ Crude oil theft (illegal) bunkering) point, ☐ Third party tampering with Clamp Third party tampering with valve setting, ☐ Third party tampering with flange,

Outward dent

□Valve Failure
□Com unit failure
□Cold vent
□Relief valve failure
□Cohers (specify) NTERNAL EROSIO
ON AVA UNIT

f. Incident caused by:
□Third party interference
□Operational
□Mystery

☐ Saver-pit over flow,

☐Surge vessel overflow

Corresion

g. Spill point coordinates

Measuring unit

Northing: 48590. 72m

Easting: 428448. 47m

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0527 900126

C.	RISK ASSESSI	MENT			
	10. Ty	pe of environment:			
	☐ Land	□ Swamp	Water	☐ Seasonal swam	np
	i. Tyj	pe of environment to	which oil has spre	ad: No IMPACT TIME OF	WAS OBSERVED AT INVESTIGATION.
	☐ Land	☐ Swamp	√ Water	☐ River (identify	
	ii. We	eather condition			
	☐ Raining	Sunny om the nearest sensitiv	ve habitat		
	☐ Drinkir☐ Built up ☐ Farmla☐ Fish Fa☐ Fishing☐ Others	nds arm/Pond g net		[ [ [ [	,m] ,m] ,m] ,m] ,m]
	Booms	☐ Trench	□ Dyke		
	☐ Others:				
	13. Any picture	es or video coverage?		[Y]	[ N ]
	14. Was there a	any disruption to the i	nvestigation?	[Y]	[N]
lf 	yes give brief des	cription:	APF	LICA B	3LE
D	. TYPE/NUMBE	RS OF PROPERTI	ES, IF ANY, FOU	UND WITHIN THE	AREA OF SPREAD OF OIL

## 15. Structures / Properties

S/N Type of Structi	res Description	Size	Number	Comments
Not	APP	<u>L</u> 1(	ABLE	

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1521 900126

### 16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
ال.	•	٨				
		1/001	$1 \bigcirc \lambda$	-	,	<u></u>
		MITTE		BIF		
	, -					


#### 17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
		100110	101 E	
		TTPFIII	MBLE	
	1 4 0 1	111123	<del>- 1   </del>	

#### 18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
		£		
N X	1	$\sqrt{DDIIO}$	5	
		APPILLA	KIF	
	<b>V</b>	41110.		

E. GRAPHIC DESCRIPTION OF LEAK POINT While detail report of the leak point should be contained in the Leak report, overview sketch of the site should be added as an appendix 1)



#### THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED 0527 anoles JOINT INVESTIGATION REPORT FOR INCIDENT NO:

## F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

S/N	Northing	Easting
		./
		Peox12 2012
_		

### G. INCIDENT INFORMATION:

20	Impacted	A	Dataile
ZU.	impacted	Area	Details

	<ul> <li>Total calculated area of impact</li> <li>Impact within SPDC R.O.W</li> <li>Impact outside R.O.W</li> </ul>	NIL NIL	·	
21.	Volume of oil recovered before compl	etion of JIV (V <sub>ree</sub> J):		
	Recov	ered oil V <sub>met</sub>		barrels
20. a.	Computation of the residual volume of Computation of volume of pool of free ph		CALCUL	nait <b>a</b>

	of volume of pool of free phase oil (on land or confined water body).  Area (m²) occupied by pool of free phase oil	CALCULATION OF
		SPILLED VOLUME
ii.	Average Depth (m) of pool of free phase oil	BASED ON PRODUCTION
		CAPACITY OF WELL
		19
		(= 2,278 DARRELS
		PER DAY (NET)

		PORT FOR INCID		of nigeria limite 0527 9 <sub>0012</sub>	
JOINT INVE	STIGATION REP	OKI FOR INCID	ENTINO	AREA OF LEAK	- <del>-</del>
iii, Emulsification	factor:			(TRIANGULAR	
iv.	Volume of	pool of free phase o	il. V <sub>pool</sub> :		barrels
	. f l f i . f i		(37. )	= = X BASE X	HEIGHT
<del>-</del>		rated oil in the soil vered by the oil:	(Vinf)	-	n × 0.01m
	•	ool of free phase oil	in touch with	•	_
	•	h (m) below groun			<del>)+000</del> 2 m²,
		ii (iii) below groun	surface of fin	AREA OF 4"	DIAMETER
		porosity of the soil	).		THROUGH
		of infiltrated oil.		1 200 4 10 10 10	barrels
	70142		**************************************	WHICH WE	L PROBUGES
21. Computation		-	ased on standa		/ \
	of oil on open wate	r: n water based on cok	oration **	- <del> </del>	$(TT) \times 0.05m$
n. lable of ave	nage adpart or on o			4	X 0-05m
	Thickness (mm)	Percentaç coverage		Volume (m3)	V 0.02III
Barely Visible	0.00004			, , , , , , , , , , , , , , , , , , ,	= 0.008m2,
Silvery	0.00008			Naruea:	TICALLY,
Slight Color	-				
Bright Color Dull	0.0003			0.008m2 =	2,278 BARRELS
Dark	0.002		<del>,</del>	- 2	PER DAY
Black oil	0.1		- 1	<u></u>	0.0002
Emulsion (30% Oil)	1				800.0
_	Percent Total		100%	Total Volume	bbl
iii.	Volume of o	il on open water.	Vwat:		barrels
22. Calculation of	of evaporated vol	ume:		<i>₹</i>	56.95
i. Oil 1	type:	_	-т.	· ·	BARRELS/DAY.
ii. E-Fa	actor:		(4	HS IMPLIES TH	
_				24 HOEARS =	2509 68 <u>29-37-</u>
iii.	Volume of e	aporated oil. V evan		C. Hour =	barrels
Fyznorg	tion Factors (F.Fac	tor) for SPDC Crude	oil		•
Oil Type	Days on site	Bonny Light	Bonny	7/4	
7 10 07		100/	Medium		BARRELS
Period Since Oil Spill	< 1 day	10%	5%	_ 5.0	_
	1-7 days	25%	15%	$=$ $\frac{58.99}{0.00}$	3
	> 7 days	40%	25%	<u> </u>	= 2º37
					BARRELS
			L	EAK BURATION	
			TROM	XelxiAN -	8.200
				(TIME OF ) REPORT)	(TIME WELL)
			·	REPORT)	CWAS SHUT IN
			Page 5 of	19_ = 20 MI	
*If area is not same a ** Spill Factor from	is the total area of impo USCG FOG (2000 Edit	ct, please indicate in the	e overview sketch	THUS ! HOUR	SE 2.37
				20 MINUTES	= 00 X 84RREL
				= 0-79 64	-60 ^ BARREL
ŧ	STIMBLEN	SPILL VOLUM	= ~ n	υ-/9 64 πα <u>φών</u> α Χ <sub>εν</sub>	RREL.
L.	مراستان (۱۹۰۱۳) حسر	THE COLUMN		OUNTEL	

0527 900126 JOINT INVESTIGATION REPORT FOR INCIDENT NO: 23. Gross Total Estimated Spilled Volume  $V_{\text{Est}}(bbls) = V_{\text{evap}}(bbls) + V_{\text{wat}}(bbls) + V_{\text{inf}}(bbls) + V_{\text{pool}}(bbls) + V_{\text{recJ}}(bbls)$  $V_{Est}(bbls)=$ 0.8 BARREL 24. Net Total Estimated Spilled Volume  $V_{\text{Est}}(bbls) = V_{\text{evap}}(bbls) + 0.6*V_{\text{war}}(bbls) + V_{\text{inf}}(bbls) + V_{\text{pool}}(bbls) + V_{\text{recl}}(bbls)$ D. & BARREL VEst(bbls)= \*Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site \*Conversion of m3 to barrels is Total volume VT (m3) x 6.29 \*Emulsification factor for spill on water to consider is 60% of volume of oil. 25. GENERAL STATUS OF THE SITE A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out B. Investigation of the incident site showed that there is residual impact on site requiring further works

#### **26 REPRESENTATIVES**

This report was filled and signed on the investigation representatives from	53 / 12 /20 12 at incident site by joint
• Host Community □	
<ul> <li>Department of Petroleum Resources [</li> </ul>	DPR]: □
<ul> <li>National Oil Spill Detection and Respert</li> </ul>	onse Agency [NOSDRA]: 🗔
State Ministry of Environment [SME]	_
• Nigeria Police Force [NPF]:□	
Shell Petroleum Development Compa	ny [SPDC]:□
	Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 900126

27. Appendix 1: Overview sketch of the site

Location: NEMBE   WELL 195 WELLHEAD AT OGBOLD MARK!
. SWAMPY TERRAIN
· · · · · · · · · · · · · · · · · · ·
WELL HEAD
WAIL HEAD
OPEN WATER TIGHTONY
OPEN WATER TONY,  DESERVED INVESTIGATIONS,
- BESERO INVEST
DURING (
POSITION BOOM
POSITION BOOM
_ 74

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 5527 900126

# 21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
		7
		Reg 1 1
		03/12/2012