



Close-up: Position of internal erosion on Nembe 1 Well 19S Wellhead at Ogbolomabiri.
Picture was taken during Joint Investigation of 3rd Dec. 2012.