



Close up: Illegal fittings on 24" Nkpoku-Bomu pipeline at Biara. Picture was taken during Joint Investigation of 9<sup>th</sup> November 2012.