



Overview: Part of spill impact on Imo River1 Well25S flowline right of way at Owaza. Picture was taken during Joint Investigation of 16th November 2012.



Close up: Cut sections on Imo River1 Well25S flowline at Owaza. Picture was taken during Joint Investigation of 16th November 2012.