



Overview: Part of spill impact on 12 inch Imo River 1 and 2- Ogale Pipeline at Komkom.
Picture was taken during Joint Investigation of 8th Nov. 2012.



Overview: Part of spill impact on 12 inch Imo River 1 and 2- Ogale Pipeline at Komkom.
Picture was taken during overfly assessment on 10th Nov. 2012.



Close-up: Illegal fittings on 12 inch Imo River1 and 2- Ogale Pipeline at Komkom.
Picture was taken during Joint Investigation of 11th Nov. 2012



Close-up: Illegal fittings on 12 inch Imo River1 and 2- Ogale Pipeline at Komkom.
Picture was taken during Joint Investigation of 8th Nov. 2012