



Overview: Part of spill impact Cawthorne Channel 2 Well 28T at Owame-Ama Okpoama.
Picture was taken during Joint Investigation of 28th Nov. 2012.



Close-up: Failed Clamp on Cawthorne Channel 2 Well 28T at Owame-Ama Okpoama.
Picture was taken during Joint Investigation of 28th Nov. 2012.