



Overview: Part of spill impact on 20 inch Otumara - Escravos Pipeline at Escravos.
Picture was taken during Joint Investigation of 24th Nov. 2012.



Close-up: Illegal fitting on 20 inch Otumara - Escravos Pipeline at Escravos.
Picture was taken during Joint Investigation of 24th Nov. 2012.