



Overview: Part of spill impact on 24 inch Nkpoku – Bomu Pipeline at Egbalor.
Picture was taken during Joint Investigation of 1st Dec. 2012.



Close-up: Hacksaw cut on 24 inch Nkpoku – Bomu Pipeline at Egbalor.
Picture was taken during Joint Investigation of 1st Dec. 2012.