



Overview: Part of spill impact on 24" Bomu-Bonny pipeline right of way at Mogho. Picture was taken during Joint Investigation of 15th November 2012.



Close up: Illegal fitting on 24" Bomu-Bonny pipeline at Mogho. Picture was taken during Joint Investigation of 16th November 2012.