



Overview: Part of spill impact on 8" Obigbo North-Komkom pipeline right of way at Umuokolobo. Picture was taken during Joint Investigation of 14th November 2012.



Close up: Illegal fitting on 8" Obigbo North-Komkom pipeline at Umuokolobo. Picture was taken during Joint Investigation of 14th November 2012.