



Overview: Part of spill impact on Imo River1 Well18 flowline right of way at Owaza. Picture was taken during Joint Investigation of 16th November 2012.



Close up: Cut section on Imo River1 Well18 flowline at Owaza. Picture was taken during Joint Investigation of 16th November 2012.