



Overview: Part of spill impact on 12" Imo River2 – Oghale pipeline right of way at Uzuaku. Picture was taken during Joint Investigation of 19th November 2012.



Close up: Illegal fitting on 12" Imo River2 – Oghale pipeline at Uzuaku. Picture was taken during Joint Investigation of 19th November 2012.