



Overview: Part of spill impact on 20" Otumara-Escravos pipeline right of way at Adjudiabo. Picture was taken during Joint Investigation of 25th September 2012.



Close up: Illegal fitting on 20" Otumara-Escravos pipeline at Adjudiabo. Picture was taken during Joint Investigation of 25th September 2012.



Close up: Illegal fitting on 20" Otumara-Escravos pipeline at Ugboegungun. Picture was taken during Joint Investigation of 25th September 2012.