



Overview: Part of spill impact on 28" Nkoku-Bomu pipeline right of way at Elenwo. Picture was taken during Joint Investigation of 30th October 2012.



Close up: Illegal fittings on 28" Nkoku-Bomu pipeline at Elenwo. Picture was taken during Joint Investigation of 30th October 2012.