



Overview: Part of spill impact on 12" Imo River 2 pipeline right of way at Umuedeokwara. Picture was taken during Joint Investigation of 28th October 2012.



Close up: Illegal fitting on 12" Imo River 2 pipeline at Umuedeokwara. Picture was taken during Joint Investigation of 28th October 2012.