



Overview: Part of spill impact on 28" Nkpoku-Bomu TNP at Gio. Picture was taken during Joint Investigation of 11th Sept. 2012.



Close-up: Illegal fitting on 28" Nkpoku-Bomu TNP at Gio. Picture was taken during Joint Investigation of 13th Sept. 2012.