



Overview: Part of spill impact on 4" Obelle-Ibaa pipeline right of way at Ibaa. Picture was taken during Joint Investigation of 27th September 2012.



Close up: Hacksaw cut on 4" Obelle-Ibaa pipeline at Ibaa. Picture was taken during Joint Investigation of 28th September 2012.