



Overview: Part of spill impact on 16" Uzere - Eriemu Trunkline at Iyede. Picture was taken during Joint Investigation of 18th Sept. 2012.



Close-up: Drilled hole on 16" Uzere - Eriemu Trunkline at Iyede. Picture was taken during Joint Investigation of 18th Sept. 2012.