



Overview: Part of spill impact on Uzere Well 12 Flowline at Ezede-Uzere.  
Picture was taken during Joint Investigation of 25<sup>th</sup> Sept. 2012.



Close-up: Missing Flowline on Uzere Well 12 Flowline at Ezede-Uzere.  
Picture was taken during Joint Investigation of 25<sup>th</sup> Sept. 2012.



Close-up: Missing Flowline on Uzere Well 12 Flowline at Ezede-Uzere.  
Picture was taken during Joint Investigation of 25<sup>th</sup> Sept. 2012.