



Overview: Part of spill impact on 10" Nun River delivery line right of way at Ekowe. Picture was taken during Joint Investigation of 25<sup>th</sup> October 2012.



Close up: Hacksaw cut on 10" Nun River delivery line at Ekowe. Picture was taken during Joint Investigation of 25<sup>th</sup> October 2012.