

(Note: As practicable as possible the JIT report is to be signed in t	the field by all the participating parties)
A. GENERAL INFORMATION:	
	e of incident * OIL SPILL
3. Name of Location 4" CBELLE - 18AA PL	
4. Name of nearest community 18AA 5. State: R	IVEZS 6. LGA EMOHIA
7. Type of Production facility/Installation PIPELINE 8	
B. INCIDENT INFORMATION:	
9. Details of incident a. Date of incident: 24 TH SEPTEMBER, 2012. b. Start date/time of investigation: 27 TH SEPTEMBER, c. Investigation End date: 28 TH SEPTEMBER, d. Description of spill point environment	
Firmed soil Loose soil	Previously excavated area
☐Under water ☐Swampy	Exposed pipe surface
☐ Well Plateform (on Water) e. Description of leak point (tick as applicable);	\square_{Rig}
Drilled hole	☐Explosive tear,
□Complete Rupture □ Inward dent,	☐ Well head tampering
Failed Weld-on illegal hot tap valve,	☐ Missing Pipeline/Flowline)
Crude oil theft (illegal) bunkering) point,	☐ Third party tampering with Clamp
Third party tampering with valve setting,	☐ Third party tampering with flange,
□Corrosion □Saver-pit over flow	
Outward dent	-
Uvalve Failure Com unit failure	Cold vent
☐Relief valve failure ☐Others (specify)	— Cold Vent
f. Incident caused by: Third party interference Operational	□Mystery
g. Spill point coordinates Measuring unit Me Yea. (MINHA	MID-REIT)
Northing:	Easting:
SP 107605.623	492587.218
	·

Page 1 of 9

^{. *}This can be a) Oil spill b) Drilling fluid/Chemical c) siltation d) construction e) Encroachment f) Fire,

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0356-37061

C.	RISK ASSESSMEN	NT			
	10. Type o	of environment:			
	Land	□ Swamp	□ Water	□ Scasonal swamp	
	i. Type of	f environment to	which oil has spre	ead:	
	Land	☐ Swamp	□ Water	□ River (identify)	
	ii. Weathe	r condition			
	☐ Raining 11. Distance from th	Sunny se nearest sensiti	ive habitat		
	☐ Drinking wa☐ Built up are☐ Farmlands☐ Fish Farm/P☐ Fishing net	ater source a cond cify). Phend	TREES PLANT	[,m] [,m] [,m] [,m]	
	□ Booms	Trench	□ Dyke		
	☐ Others:	.			
	13. Any pictures or	video coverage?	,	[Y] [N]	
	14. Was there any d	isruption to the i	investigation?	[Y] [N]	
fy	es give brief description	on:			
	NOT	AT	PLICA	RLE	-
D.	TYPE/NUMBERS C)F PROPERTI	ES, IF ANY, FOU	ND WITHIN THE AREA OF SPREAD OF OIL	
	15. Structures / Pro	operties			

S/N	Type of Structures	Description	Size	Number	_	Comments
	NONE	WITH	M	AREA	oF	MPACT

JOINT INVESTIGATION REPORT FOR INCIDENT NO:___

0356-8706EI

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	NONE	William	ARC	A OF	MPA	\overline{C}
	_					

17. Fish/Nets/Ponds


S/N Fish/Nets/Ponds	Description	Quantity/Size	Comments
NONE M	THIN ARE	1 70 /	APACT

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
		7 1		HAADE OF
	10N 1=	- M [#] M	AKGA OF	(MAKE)
 	<u> </u>			

E. GRAPHIC DESCRIPTION OF LEAK POINT While detail report of the leak point should be contained in the Leak report, overview sketch of the site should be added as an appendix 1)

SECTION OF 4" OBELE - IBAA PIPELINE AT IBAA SHOWING POSITION OF HACKSAW CUT.



Page 3 of 9

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: \$356 - \$70661

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION 19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

S/N	Winna -	Mid belt.
5/14	Northing (M)	Easting (M)
BRI	107389.313	482169.6
BKZ	107397.77	482173.796
BRG	107400.755	482207.697
BN 7	107400. 723	482220.022
BR8	107406.812	482241.607
13R9	107403.70	482257.005
BN 26	107418.855	482337.156
BR25	107415.743	482352 555
181224	107 406. 478	482371.018
BR21	107 406 . 439	482386.424
BX-23	107406.391	482404.912
BR35A	107464 - 638	482454.362
BR46	<u> </u>	482479.193

G. INCIDENT INFORMATION:

20. In	pacted	Area	Details
--------	--------	------	----------------

Total calculated area of impact Impact within SPDC R.O.W	0.812075ha	
Impact outside R.O.W	7€5	
21. Volume of oil recovered before complete	ion of JIV (V _{recJ}):	
Récover	ed oil Vat	barrels
 20. Computation of the residual volume on s a. Computation of volume of pool of free phase i. Area (m²) occupied by pool of ii. Average Depth (m) of pool of 	e oil (on land or confined water body). free phase oil	<u>39·6</u> ——

	•			Y OF NIGERIA LIMITI 0356 — 870	
JOINT INVE	STIGATION REF		DENT NO:_		-0.
iii. Emulsificatio	n factor:N	11_			
iv.	Volume of	pool of free phase	oil. V _{pool} :	76-6	barrels
Computation of Computation Computation Computation Computation Computation Computation Computation	i Area *(m²) co ii Area of the po iii Average Depa iv Soil type: v P _e (effective iv. Volume in of volume of oil on open wat	overed by the oil:_ ool of free phase of th (m) below ground porosity of the soil of infiltrated oil.	il in touch wind surface of	infiltration of oil: 0 C	Description of the latest the lat
•	rerage depth of oil of	••••	ioration • •		
	Thickness (mm)	Percenta coverag		Volume (m3)	_
Barely Visible	0.00004	<u> </u>			
Silvery		_			_
Slight Colo		<u> </u>	10T		4
Bright Colo		<u> </u>	TEGA.	ICARIE .	4
Dull			<u>``\\</u> `\ <u>\</u>	CUBLL	4
Dark					4
Blackoil					4
Emulsion (30% Oi	I) <u> 1</u>				」 ──
	Percent Total		100%	Total Volume NIL	bbl
iii.	Volume of c	il on open water.	Vwat	Nil	barrels
22. Calculation	of evaporated vo	lume:			
i. Oil	type: Bonni M	<u>le</u> blum.			
ii. E-l	Factor: 15 ¹ /	<u> </u>			
iii.	Volume of e	vaporated oil. V 🛶		14.34	barrels
Fronc	ration Factors (E-Fac	ctor) for SPDC Care	de oil		
Oil Type	Days on site	Bonny Light	Bonny		
0.1.1.JPC			Medium		
Period Since Oil Spill	< 1 day	10%	5%		
	1-7 days	25%	15%		

40%


>7 days

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0356 - \$7066
23. Gross Total Estimated Spilled Volume
$V_{\text{Est}}(bbls) = V_{\text{evap}}(bbls) + V_{\text{wat}}(bbls) + V_{\text{inf}}(bbls) + V_{\text{pool}}(bbls) + V_{\text{recJ}}(bbls)$
VEST (bbls) = 14.34 + ML + (3.76 + 1.01) + 76.6 = 95.71 Brecels
24. <u>Net Total Estimated Spilled Volume</u>
$V_{\text{Est}}(bbls) = V_{\text{evap}}(bbls) + 0.6*V_{\text{wat}}(bbls) + V_{\text{inf}}(bbls) + V_{\text{pool}}(bbls) + V_{\text{recJ}}(bbls)$
VEST(bbls)= 95.7 BARREL.
*Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site
*Conversion of m3 to barrels is Total volume VT (m3) x 6.29
*Emulsification factor for spill on water to consider is 60% of volume of oil.
25. GENERAL STATUS OF THE SITE
A. Joint investigation of the incident site found that there is no residual impact after the
initial response and therefore recommend that the site be closed out
B. Investigation of the incident site showed that there is residual impact on site requiring
further works 🗹
26 REPRESENTATIVES
This report was filled and signed on the investigation representatives from $\frac{25/60/2012}{2012}$ at incident site by joint
• Host Community
• Department of Petroleum Resources [DPR]:
National Oil Spill Detection and Response Agency [NOSDRA]: ✓
State Ministry of Environment [SME]:
• Nigeria Police Force [NPF]: 🔀
Shell Petroleum Development Company [SPDC]:

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0356 - 870661

27. Appendix 1: Overview sketch of the site



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1356 - 270661

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION (MINNA MID-LET)

S/N Northing Easting (METEC) (METES) BR 49 107608.71 482581.064 BR54 107617.936 482578.006 BR51 107614.816 482.596.485 BR52 107 356. 814 482,568.09 221 BR 52 482546 529 QCC 1073 & 941 482546.529. BR53 107359.941 482581.056 GLSO 107 605.639 107 535. 229 482482.275 BN 39 107 467 678 B1236 82466.694 BR 30 107394.110 82401·799 BR 20 107403.414 82367-929 BN 19 482352.547 107412.671 482334.067 18R18 107 415.791 482223.064 BOL 5 107385-353 482201.487 BR4 107382-337 482183.008 107385.457 1323 482580.755 107 488.891 AΙ 107 362.966 492565 025 A 482 561.944 Az 107 362 .974 482577.674 A-4