



Overview: Part of spill impact on 8" Ubie pipeline manifold right of way at Ukpeliède. Picture was taken during Joint Investigation of 26<sup>th</sup> October 2012.



Close up: Leak from barrel door on 8" Ubie pipeline manifold at Ukpeliède. Picture was taken during Joint Investigation of 26<sup>th</sup> October 2012.