



Overview: Part of spill impact on 28" Nkpoku - Bomu Pipeline at Gio.  
Picture was taken during Joint Investigation of 24<sup>th</sup> Sept. 2012.



Close-up: Illegal fitting on 28" Nkpoku - Bomu Pipeline at Gio.  
Picture was taken during Joint Investigation of 24<sup>th</sup> Sept. 2012.