



Overview: Part of spill impact on Benisede Well 15T at Ojobo. Picture was taken during Joint Investigation of 12th Sept. 2012.



Close-up: Illegal Wellhead tampering on Benisede Well 15T at Ojobo. Picture was taken during Joint Investigation of 12th Sept. 2012.