



Overview: Part of spill impact on 20" Opukushi-Brass Creek Trunkline at Opukushi.
Picture was taken during Joint Investigation of 28th Sept. 2012.



Close-up: Illegal fitting on 20" Opukushi-Brass Creek Trunkline at Opukushi.
Picture was taken during Joint Investigation of 29th Sept. 2012.