



Overview: Part of spill impact on 16'' Uzere-Eriemu Pipeline at Iyede. Picture was taken during Joint Investigation of 13<sup>th</sup> Sept. 2012.



Close-up: Illegal fittings on 16'' Uzere-Eriemu Pipeline at Iyede. Picture was taken during Joint Investigation of 13<sup>th</sup> Sept. 2012.