



Overview: Part of spill impact on 20'' Buguma-Alakiri Trunkline at Daily Bread (Bukuma). Picture was taken during Joint Investigation of 23<sup>rd</sup> Sept. 2012.



Close-up: Illegal fitting on 20'' Buguma-Alakiri Trunkline at Daily Bread (Bukuma). Picture was taken during Joint Investigation of 23<sup>rd</sup> Sept. 2012.