



Overview: Part of spill impact on 18" Assa - Rumuekpe Trunkline at Awara. Picture was taken during Joint Investigation of 19th Sept. 2012.



Close-up: Failed clamp on 18" Assa - Rumuekpe Trunkline at Awara. Picture was taken during Joint Investigation of 19th Sept. 2012..