



Overview: Part of spill impact on Cawthorne Channel 1 Well 49L at Cawthorne Channel.  
Picture was taken during Joint Investigation of 19th Sept. 2012.



Close-up: Hacksaw cut on Cawthorne Channel 1 Well 49L at Cawthorne Channel.  
Picture was taken during Joint Investigation of 19th Sept. 2012.