



Overview: Part of spill impact on Benisede Well 11 flowline at Amabulou. Picture was taken during Joint Investigation of 30<sup>th</sup> April 2013.



Close up: Illegal fittings on Benisede Well 11 flowline at Amabulou. Picture was taken during Joint Investigation of 30<sup>th</sup> April 2013.