



Overview: Part of spill impact on 24" NembeCreek pipeline right of way at Kalibiama. Picture was taken during Joint Investigation of 25<sup>th</sup> April 2013.



Close up: Illegal fitting on 24" NembeCreek pipeline at Kalibiama. Picture was taken during Joint Investigation of 26<sup>th</sup> April 2013.