



Overview: Part of spill impact on 24" Nkpoku-Bomu Trans Niger pipeline at Eelenwo. Picture was taken during Joint Investigation of 28<sup>th</sup> April 2013.



Close up: Illegal fittings on 24" Nkpoku-Bomu Trans Niger pipeline at Eelenwo. Picture was taken during Joint Investigation of 1<sup>st</sup> May 2013.