



Overview: Part of spill impact at Assa manifold. Picture was taken during Joint Investigation of 3rd May 2013.



Close up: Leaking barrel door at Assa manifold. Picture was taken during Joint Investigation of 3rd May 2013.