



Overview: Part of spill impact on Nembe1 Well23T flowline right of way at Ewesuo. Picture was taken during Joint Investigation of 16th April 2013.



Close up: Cut section on Nembe1 Well23T flowline at Ewesuo. Picture was taken during Joint Investigation of 16th April 2013.