



Overview: Part of spill impact on 20" Opukushi - Brass Creek Pipeline at Tamogbene.
Picture was taken during Joint Investigation of 17th April 2013.



Close up: Illegal fittings on 20" Opukushi - Brass Creek Pipeline at Tamogbene.
Picture was taken during Joint Investigation of 16th April 2013.