



Overview: Part of spill impact on 20" Opukushi-Brass Creek trunkline right of way at Tamogbene. Picture was taken during Joint Investigation of 14<sup>th</sup> May 2013.



Close up: Illegal fitting on 20" Opukushi-Brass Creek trunkline at Tamogbene. Picture was taken during Joint Investigation of 14<sup>th</sup> May 2013.