



Overview: Part of spill impact on 12" Oguta-Egbema pipeline right of way at Opuoma-Oguta. Picture was taken during Joint Investigation of 10th April 2013.



Close up: Illegal fittings on 12" Oguta-Egbema pipeline at Opuoma-Oguta. Picture was taken during Joint Investigation of 10th April 2013.