



Overview: Part of spill impact on 6" Obigbo North-Ogale pipeline right of way at Ogale. Picture was taken during Joint Investigation of 27th August 2013.



Close up: Illegal fitting on 6" Obigbo North-Ogale pipeline at Ogale. Picture was taken during Joint Investigation of 28th August 2013.