



Overview: Part of spill impact on Awoba Well3S flowline right of way at Bille. Picture was taken during Joint Investigation of 11th September 2013.



Close up: Hacksaw cut on Awoba Well3S flowline at Bille. Picture was taken during Joint Investigation of 11th September 2013.