



Overview: Part of spill impact on 14" Okordia-Rumuekpe pipeline right of way at Ikarama. Picture was taken during Joint Investigation of 13<sup>th</sup> August 2013.



Close up: Leak due to corrosion at 6 o' clock position on 14" Okordia-Rumuekpe pipeline at Ikarama. Picture was taken during Joint Investigation of 13<sup>th</sup> August 2013.