



Overview: Part of spill impact on 16" Nun River – Kolocreek pipeline right of way at Igiebiri. Picture was taken during Joint Investigation of 28th August 2013.



Close upHacksaw cut on 16" Nun River – Kolocreek pipeline at Igiebiri. Picture was taken during Joint Investigation of 28th August 2013.