



Overview: Part of spill impact on 12" Imo River2 – Ogale pipeline right of way at Umuedeokwara/Odagwa. Picture was taken during Joint Investigation of 6<sup>th</sup> August 2013.



Close up: Illegal fittings on 12" Imo River2 – Ogale pipeline at Umuedeokwara/Odagwa. Picture was taken during Joint Investigation of 6<sup>th</sup> August 2013.