



Overview: Part of spill impact on 24" Cawthorne-Channel loopline manifold right of way at Ilomaturu. Picture was taken during Joint Investigation of 15<sup>th</sup> August 2013.



Close up: Position of missing pressure gauge at 24" Cawthorne-Channel loopline manifold at Ilomaturu. Picture was taken during Joint Investigation of 15<sup>th</sup> August 2013.