



Overview: Part of spill impact on 6" Cawthorne Channel Well45T flowline right of way at Mbiama. Picture was taken during Joint Investigation of 21st August 2013.



Close up: Drilled surface on 6" Cawthorne Channel Well45T flowline at Mbiama. Picture was taken during Joint Investigation of 21st August 2013.